




<b>Model:</b>	880102 - Acute Momentum Recliner										
<b>Specifications:</b>	29.5W	33D	43H	23SW	20.5SD	19SH	26AH	65ED	95LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2588	\$2638	\$2747	\$2786	\$2846	\$2972	\$3086	\$3287	\$3413	\$3540	\$2262
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$227										



<b>Model:</b>	880302 - Acute Momentum Rocker Recliner										
<b>Specifications:</b>	28.25W	32D	43H	22.75SW	20.5SD	19SH	25.5AH	65ED	120LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2588	\$2638	\$2747	\$2786	\$2846	\$2972	\$3086	\$3287	\$3413	\$3540	\$2262
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$227										



<b>Model:</b>	880502 - Acute Momentum Trendelenburg Recliner										
<b>Specifications:</b>	28.25W	32D	43H	22.75SW	20.5SD	19SH	25.5AH	66ED	106LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2588	\$2638	\$2747	\$2786	\$2846	\$2972	\$3086	\$3287	\$3413	\$3540	\$2262
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$227										



<b>Model:</b>	890902 - Acute Momentum Motorized Trendelenburg										
<b>Specifications:</b>	29W	33D	43H	23SW	20.5SD	19SH	25.5AH	66ED	128LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$4469	\$4519	\$4628	\$4667	\$4727	\$4853	\$4967	\$5169	\$5295	\$5421	\$4212
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$422										