




<b>Model:</b>	880102 - Acute Momentum Recliner										
<b>Specifications:</b>	29.5W	33D	43H	23SW	20.5SD	19SH	26AH	65ED	95LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2755	\$2805	\$2914	\$2953	\$3013	\$3139	\$3252	\$3454	\$3580	\$3706	\$2435
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$244										



<b>Model:</b>	880302 - Acute Momentum Rocker Recliner										
<b>Specifications:</b>	29W	34.75D	43.5H	23.25SW	21.75SD	19SH	26AH	64.5ED	120LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2755	\$2805	\$2914	\$2953	\$3013	\$3139	\$3252	\$3454	\$3580	\$3706	\$2435
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$244										



<b>Model:</b>	880502 - Acute Momentum Trendelenburg Recliner										
<b>Specifications:</b>	28.25W	32D	43H	22.75SW	20.5SD	19SH	25.5AH	66ED	106LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$2894	\$2944	\$3053	\$3092	\$3152	\$3278	\$3391	\$3593	\$3719	\$3845	\$2579
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$258										



<b>Model:</b>	890902 - Acute Momentum Motorized Trendelenburg										
<b>Specifications:</b>	29W	33D	43H	23SW	20.5SD	19SH	26AH	66ED	128LBS	8YDS	
<b>Fabric Grade:</b>	<u>7</u>	<u>8</u>	<u>9</u>	<u>10</u>	<u>11</u>	<u>12</u>	<u>13</u>	<u>14</u>	<u>15</u>	<u>16</u>	<u>COM</u>
<b>List Price:</b>	\$5018	\$5067	\$5177	\$5215	\$5275	\$5402	\$5515	\$5717	\$5843	\$5969	\$4780
<b>Options:</b>	• CAL133 \$40/yard • Moisture Barrier \$30/yard • Multiple Fabrics \$478										